



IMPORTANT: VERIFY ALL FAN MOTOR WIRING MATCHES OUTPUT VOLTAGE FROM EDRIVE (REFER TO THE CONNECTION DIAGRAM)
POWER TO THE FAN MUST BE PROVIDED BY THE EDRIVE. MOTOR COULD BE DAMAGED IF LINE VOLTAGE
IS APPLIED TO THE FAN DIRECTLY.